

- JET DRIVE KITS -
FEBRUARY 2008
YAMAHA 2 STROKE MOTORS

HP	YEAR	NO. CYL	DISPL. CU. IN.	STEERING		MOTOR SHAFT LENGTH			NOTES
				TILLER HANDLE	REMOTE CONTROL	15"	20"	25"	
25	1987-Present	2	24.1	•		BA			2
25-30	1987-2002	3	30.27	•	•	Z30R Z30M	Z30LR Z30LM		2
40-50	1983-1994	3	42.6	•	•	ZSR ZSM	ZLR ZLM		8 8
40-50	1995-Present	3	42.6	•	•	AJSR AJSM	AJLR AJLM		8 2, 8, 11
60-70	1983-2003	3	51.8	•	•		Y70		9
60-70	2004-Present	3	51.8	•	•		Y70-04		9, 10
75-90	1983-Present	3	69.6		•		Y90		
115-130	1983-Present	V4	105.5		•		AA4		
150-225	1983-Present	V6	158.4		•		AA6	AA6X	5
175-225	1991-Present	V6	158.4		•		AA6P	AA6PX	5, 7
200-250	1998-Present	V6	191.0-204.0		•		AQ	AQX	4

YAMAHA 4 STROKE MOTORS

F40	1999-Present	3	45.6	•	•	AJSR-43 AJSM-43	AJLR-43 AJLM-43		1, 8, 1,2,8,11,12
F50	1995-2005	4	57.0	•	•		AJL-44 14T AJCL-44 14T		1, 6, 8 1,2,6,8,11
F50-60	2002-Present	4	60.8	•	•		AJL-44 16T AJCL-44 16T		1, 8 1, 2, 8, 11
F75-100	1998-Present	4	97.4	•	•		Y100-4 Y100C-4		1 1, 2, 11
F115	2000-Present	4	106.2		•		AA115-4	AA115-4X	1, 11
F150	2003-Present	4	164.8		•		AW	AWX	
F200-225	2002-Present	V6	204.6		•			AQX	4

NOTES: •Y E S

- (1) 4 stroke motors need pressure relief hole in cooling pump housing. Instructions in kit.
- (2) Includes shift cable assembly for tiller steering.
- (4) Includes neutral cable assy 1566.3
- (5) Specify if for HPDI – add neutral cable 1566.3.
- (6) Driveshaft change year 2000. Specify spline, 14 or 16 teeth.
- (7) Heavier load capability than AA6 series.
- (8) Add \$150.00 for 6 1/8 stainless steel impeller, #1737.
- (9) Driveshaft change in 60-70HP 2 stroke motors starting in 2004.
- (10) Tiller handle model requires shift cable 1383.
- (11) Tiller handle change in 2006 - specify 1856 or 1857 shift cable assy for tiller steering.
- (12) 2006 tiller handle, rope start motor requires neutral start cable 1566.3.