

- JET DRIVE KITS -

FEBRUARY 2008

JOHNSON / EVINRUDE 2 STROKE MOTORS

HP	YEAR	NO. CYL	DISPL. CU. IN.	STEERING		MOTOR SHAFT LENGTH			NOTES
				TILLER HANDLE	REMOTE CONTROL	15"	20"	25"	
20-35	1976-Present	2	31.8	•	•	Q35	Q35L		2, 13
40-60	1971-1988	2	41.5-44.99		•	AB	ABL		5, 10
50-55	1971-1980	2	41.5-44.99	•		ABM	ABML		5, 10
40-60	1981-1988	2	41.5-44.99	•		ABC	ABCL		4, 5, 10
45C-55C	1989-Present	2	44.99	•		ABC	ABCL		4, 5, 8, 10
40-50	1989-1992	2	44.99		•	AF	AFL		5, 10
				•		AFC	AFCL		4, 5, 10
40-50	1993-2005	2	44.99		•	AF93	AFL93		6, 10
				•		AFC93	AFCL93		4, 6, 10
55-75	1968-1988	3	49.7-56.1		•	L60	L60L		
				•		L60C	L60CL		4, 12
50-70	1989-2005	3	56.1		•		L60L-89		
				•			L60CL-89		4, 12
85-115	1978-1991	90° V4	92.6-99.6		•		R85		3
85-115	1992-1996	90° V4	99.6		•		R85-92		3
75-130	1995-Present	60° V4	105.4		•		60° R4		16
110-140	1978-1991	90° V4	99.6-122.0		•		R140		3
120-140	1992-Present	90° V4	122.0		•		R140-92		3
150-235	1978-1991	90° V6	149.4-183.0		•		R6	R6X	3
135-200	1991-Present	60° V6	158.0		•		60° R6	60° R6X	
200-225	1992-2005	90° V6	183.0 Only		•		R6-92	R6-92X	3
200-250	1992-Present	90° V6	183.0-200.0		•		R6-92P	R6-92PX	9

EVINRUDE 2 STROKE E-TEC MOTORS (INCLUDES 60°R4, R140-92, 60°R6, AND R6-92P ABOVE)


40-50	2003-Present	2	52.7		•		ABL03		10
				•			ABCL03		10, 14
60	2004-Present	2	52.7		•		L60L04		
				•			L60CL04		14
75-90	2003-Present	3	79.0		•		60° R3		15

JOHNSON / EVINRUDE 4 STROKE MOTORS

40-50	1999-2005	3	49.7		•		U4L-4E		10
60-70	1998-2005	4	79.2		•		AP-E70		
90-115	2001-2005	4	118.9		•		AP-E90-115	AP-E90-115X	
140	2002-2005	4	124.7		•		AP-E140P	AP-E140PX	

NOTES: ● Y E S

- (2) Shift Rod Threading Tool. #465...\$50.00 AND Coupling #464 needed to later remount propeller drive
Return tool after use (except dealers) for refund. (Old gate required on motors 1976-1980, for tiller handle only)
- (3) Length (inches) from housing mounting face to end of driveshaft. Must match propeller gearbox within 1/8 inch
(Motor driveshaft length increased 7/16 inch in 1992. DO NOT USE OLDER MODEL R JET DRIVES ON 1992 MOTO)
- (4) Includes shift cable assembly for tiller steering
- (5) Rear base of engine mid-section - compare shapes:
- (6) Driveshaft Spline 3/4" Diameter, 17-teeth
- (8) Specify if driveshaft spline 14 teeth or 17 teeth (shaft 1280.1)
- (9) Heavier load capability than R6 series
- (10) Add \$150.00 for 6 1/8 stainless steel impeller, #1737.
- (12) Driveshaft spline: 4 teeth from 1968-1988; 17 teeth from 1989 to present.
- (13) Fits motors with through prop hub exhaust only.
- (14) For tiller steering, order new tiller handle #5007118.
- (15) For tiller steering, order new tiller handle #5007116.
- (16) For tiller steering, order new tiller handle #5007075.



Outboard Jets

DIVISION OF
SPECIALTY MFG. CO.
2035 EDISON AVENUE
SAN LEANDRO, CA 94577
(510) 562-6049 • FAX (510) 562-0000
www.outboardjets.com